

Carbon Monoxide Guide Chart

CO (ppm)		%COHb
20 & Above	Heavy Smoker	3.20+
20		3.20
19		3.04
18		2.88
17		2.72
16	Smoker	2.56
15		2.40
14		2.24
13		2.08
12		1.92
11		1.76
10		1.60
9	Light Smoker	1.44
8		1.28
7		1.12
6		0.96
5		0.80
4		0.64
3	Non Smoker	0.48
2		0.32
1		0.16